Message

Poulsen, Jeffrey [Jeffrey.Poulsen@parsons.com] From:

2/20/2019 7:13:17 PM Sent:

To: Mcpherson, Benjamin J (DEC) [benjamin.mcpherson@dec.ny.gov]; Lisichenko, Peter [lisichenko.peter@epa.gov] CC: Sweitzer, Mark [Mark.Sweitzer@Honeywell.com]; Glaza, Edward [Edward.Glaza@parsons.com]; Coladonato, Steve

[Steven.Coladonato@Honeywell.com]; Prohaska, Ronald [Ronald.Prohaska@parsons.com]; Alen Trpevski

[atrpevski@oscinc.com]; Dale@allendesnoyers.com; Harkay, Dan [Harkay, Dan@epa.gov]; Reuben, Peter A (DEC)

[peter.reuben@dec.ny.gov]; Staniszewski, Chad (DEC) [chad.staniszewski@dec.ny.gov]; Abrams, Tom

[Tom.Abrams@parsons.com]

RE: Tonawanda Coke Site 108 Subject:

Ben,

We have talked to Pariso;

The clay material that is stockpiled at the yard on river road originated from the: First Source Job Site located at 100 Pirson Pkwy, Tonawanda NY 14150

I hope that this answers any questions that you have.

Jeff

Jeffrey Poulsen, PG LEED-AP Project Manager/Principal Geologist

jeffrey.poulsen@parsons.com 716.432.7685 Mobile

From: Mcpherson, Benjamin J (DEC) <benjamin.mcpherson@dec.ny.gov>

Sent: Tuesday, February 19, 2019 7:24 PM

To: Poulsen, Jeffrey <Jeffrey.Poulsen@parsons.com>; Lisichenko, Peter <lisichenko.peter@epa.gov>

Cc: Sweitzer, Mark <Mark.Sweitzer@Honeywell.com>; Glaza, Edward <Edward.Glaza@parsons.com>; Coladonato, Steve

<Steven.Coladonato@Honeywell.com>; Prohaska, Ronald <Ronald.Prohaska@parsons.com>; Alen Trpevski

<atrpevski@oscinc.com>; Dale@allendesnoyers.com; Harkay, Dan <Harkay.Dan@epa.gov>; Reuben, Peter A (DEC)

<peter.reuben@dec.ny.gov>; Staniszewski, Chad (DEC) <chad.staniszewski@dec.ny.gov>; Abrams, Tom

<Tom.Abrams@parsons.com>

Subject: Re: Tonawanda Coke Site 108

Jeff.

Please inquire with Pariso Logistics and determine the project/address where the soil originated.

Thank you,

Ben

Benjamin McPherson, P.E.

Assistant Engineer (Environmental), Division of Environmental Remediation New York State Department of Environmental Conservation 270 Michigan Avenue, Buffalo, NY 14203

P: (716) 851-7220 | F: (716) 851-7226 | benjamin.mcpherson@dec.ny.gov

From: Poulsen, Jeffrey < Jeffrey.Poulsen@parsons.com >

Sent: Tuesday, February 19, 2019 4:57:37 PM

To: Lisichenko, Peter

Cc: Sweitzer, Mark; Glaza, Edward; Coladonato, Steve; Prohaska, Ronald; Alen Trpevski; Dale@allendesnoyers.com;

Harkay, Dan; Mcpherson, Benjamin J (DEC); Reuben, Peter A (DEC); Staniszewski, Chad (DEC); Abrams, Tom

Subject: RE: Tonawanda Coke Site 108

ATTENTION: This email come from an external source. Do not open attachments or click on links from unknown senders or unexpected emails.

Peter,

On behalf of Honeywell, Parsons has completed the sampling of the clay soil stockpile which we would like to import to the Area 108 Site.

This material will be used for berm stabilization as described in the approved work plan.

We look forward to your review of the attached and approve for the import of the fill.

Jeff Poulsen

Jeffrey Poulsen, PG LEED-AP
Project Manager/Principal Geologist
jeffrey poulsen@parsons.com
716.432.7685 Mobile

From: Lisichenko, Peter < lisichenko.peter@epa.gov>

Sent: Friday, February 15, 2019 5:40 PM

To: Abrams, Tom < Tom. Abrams@parsons.com>

Cc: Sweitzer, Mark < Mark. Sweitzer@Honeywell.com >; Glaza, Edward < Edward. Glaza@parsons.com >; Coladonato, Steve < Steven. Coladonato@Honeywell.com >; Poulsen, Jeffrey < Jeffrey. Poulsen@parsons.com >; Prohaska, Ronald < Ronald. Prohaska@parsons.com >; Alen Trpevski < atrpevski@oscinc.com >; Dale Desnoyer (dale@allendesnoyers.com) < dale@allendesnoyers.com >; Budroe, Thomas < Budroe. Thomas@epa.gov >; Harkay, Dan < Harkay. Dan@epa.gov >;

Mcpherson, Benjamin J (DEC) < benjamin.mcpherson@dec.ny.gov; Peter Reuben < peter.reuben@dec.ny.gov; Chad Staniszewski (DEC) < chad.staniszewski@dec.ny.gov

Subject: Re: Tonawanda Coke Site 108

Hi Tom,

Thank you for the update.

Please have the data summarized in data tables and compared to NYS DER-10 standards once finalized. Any exceedances should be highlighted.

Best regards,

-Pete

Sent from a mobile device

Peter Lisichenko
On-Scene Coordinator
Region 2 USEPA
347-276-6251

On Feb 15, 2019, at 4:25 PM, Abrams, Tom <Tom.Abrams@parsons.com> wrote:

Pete, Wanted to give you a status update before I leave for vacation (out next week).

- 1. Jeff Poulsen (716.432.7685) is coordinating with DEC on Material Import paperwork. Preliminary data is in and material looks good.
- 2. Planning on doing berm work and soil pile covering w/o 2/25.
- 3. Ron Prohaska (716.564.7033) is coordinating with OSC on start of work, including evaluating projected weather conditions. Ron will confirm start arrangements with you later next week.
- 4. Arranging rental of onsite roll off with WTS.

Please call me if you would like to discuss. Thanks.

Tom

Thomas	H	Ahra	me

Senior Project Manager
Suite 350
301 Plainfield Road, Syracuse, New York 13212
tom.abrams@parsons.com - (Direct Office Line) 315.552.9670; (Cell) 315.263.5109

PARSONS -	Envision	More		
www.parsoi	ns.com	LinkedIn	Twitter	Facebool
The latter lawy count in England. The Sa may have lawn morel, more	, w lakeni. Yang lakelah kelanya kala mandaka milansa	•		

'NOTICE: This email message and all attachments transmitted with it may contain privileged and confidential information, and information that is protected by, and proprietary to, Parsons Corporation, and is intended solely for the use of the addressee for the specific purpose set forth in this communication. If the reader of this message is not the intended recipient, you are hereby notified that any reading, dissemination, distribution, copying, or other use of this message or its attachments is strictly prohibited, and you should delete this message and all copies and backups thereof. The recipient may not further distribute or use any of the information contained herein without the express written authorization of the sender. If you have received this message in error, or if you have any questions regarding the use of the proprietary information contained therein, please contact the sender of this message immediately, and the sender will provide you with further instructions.'

The content image001.jpg of type has been blocked.